



Case Study One




Michael J. Schulz
Fire and Explosion Analyst
Fire and Safety Engineering Technologist


M.J. Schulz & Associates, Inc.
 4N600 Powis Road
 Wayne, Illinois 60185

Telephone – (630) 762-4926
 Facsimile – (630) 762-4928

www.mjschulz.com




DISCUSSION TOPICS



1 Discussion Topics

Case Study Background 2

3 Discussion/Questions




4 Case Study Diagram

Discussion/Questions 5


6 Copyright Notice




CASE STUDY BACKGROUND




Case Study Background





Case Study Background

- Involved apartment complex recently received final certificate of occupancy






Case Study Background





- Involved building had only two (2) units occupied at the time of the fire




Case Study Background

- Fire incident primarily limited to a single apartment unit





Case Study Background



- Adult occupant of involved apartment had entered into a one (1) year lease



Case Study Background

- Possession of the involved apartment by the occupants occurred several months prior to the occurrence of the hostile fire incident






Case Study Background




- Involved apartment occupied by single adult female and juvenile daughter



Case Study Background

- Adult occupant of the involved apartment was furloughed from her employment several weeks prior to the hostile fire incident







Case Study Background




- Hostile fire incident occurred on the first day of the heating season



CASE STUDY DIAGRAM



Case Study Diagram





DISCUSSION/QUESTIONS



